

Working in P2 classified lab

Only max. 3 groups inside P2 at a time due to limited working space.

Introduction to the P2 lab is carried out by the supervisor.

In general:

1. Leave your own lab coats, course material, protocols, pencils, etc. outside P2 lab.
2. Wear the lab coats and shoe covers which are provided in P2 lab.
3. Wear protective gloves when working.
4. All waste, syringes etc. go into special waste-containers (metal buckets, yellow-cap boxes).
5. Wash your hands before leaving P2 lab.